

כ"ה באייר, התשע"ב  
17 מאי 2012  
סימוכין : 08170512

## הודעה לימאים/(משיטים) מס' 004\2012

בהתאם לסמכותי בתקנות הנמלים (בטיחות השייט) התשמ"ג 1982 הפרק ה-8.

### הנדון : תיקון תקלת בטיחות באופנועי ים מסוג YAMAHA

1. חברת YAMAHA פרסמה הודעה כי באופנועי ים מדגמי VX1800 ו- VX1800A משנות ייצור 2011 ו-2012 יש פגם בגיט. יצאה הודעה מטעם החברה להחלפת הגיט (NOZZLE).

בעלי אופנוע ים מהדגמים ושנות הייצור הנ"ל נדרשים לפנות ליבואן הרשמי של חברת YAMAHA על מנת להחליף את החלק הפגום.

על בעלי כלי השייט מדגמים אלו להציג במשרדנו אישור על החלפת החלק כתנאי לחידוש רישיון השייט ובדיקתו.

רצ"ב: העתק מהודעת החברה.

2. מנהלי מרינות מתבקשים לפרסם הודעה זו על גבי לוחות המודעות.

**בכבוד רב,**

עמוס נוימן – מנהל אגף

כלי שיט קטנים ומשיטים



**YAMAHA MOTOR CO.,LTD.**

Water Vehicle Business Unit  
1400 Nippashi, Minami Hamamatsu, Shizuoka 432-8528, JAPAN

TEL: 81-53-441-7605  
FAX: 81-53-441-3106

TO : All Distributors  
ATTN : Marine Service Managers

No. WV-12002  
Page: 1/  
Date: April 16, 2012

FROM : Water Vehicle Planning Division.  
YAMAHA MOTOR CO., LTD. JAPAN  
SUBJECT: Jet Pump Nozzle Replacement

Model : 2011 & 2012 VX1800(A) Water Vehicles  
**FACTORY MODIFICATION CAMPAIGN**

Dear Sirs,

Thank you very much for your continuous cooperation given to Yamaha sales and service activities.

Please be advised of the possible defect relating to the following Yamaha Water Vehicles and our intention to launch a recall campaign.

Yamaha Motor Co., Ltd has decided that a possible defect which relates to safety may exist in certain 2011 and 2012 VX1800/VX1800A models Yamaha Water Vehicles.

In the affected Water Vehicles, the jet nozzle could crack during operation.

If this occurs while vehicle is underway, the nozzle will leak jet thrust, resulting in reduced steering ability, as well as reduced acceleration and top speed.

Reduced control could cause in an accident resulting injury or death.

If Applicable, report to your respective government agencies regarding the safety recall campaign within the time limits prescribed by law.

The distributors must issue a Safety Recall Campaign Bulletin to all dealers and a customer letter to notify all the registered owners of affected units.

The dealers must modify all affected units in their inventory as well as all the customer owned units brought to them for this modification.

Please instruct all customers to contact their dealers immediately to arrange an appointment to have the modification carried out.

Please find enclosed TSI for details of this matter.

Your kind understanding and cooperation with this recall campaign are highly appreciated.

Yours faithfully,  
Yamaha Motor Co., Ltd.

Satoshi Ando  
General Manager  
Planning Division  
Water Vehicle Business Unit